

दिल्ली नगर निगम




MUNICIPAL CORPORATION OF DELHI  
OFFICE OF THE EXECUTIVE  
ENGINEER (ROHINI) -II  
ROAD NO-44, PITAM PURA VILL.  
DELHI-110034

No:-EE(Rohini)II/D-938

Dated :- 21/08/2002

Sub:- Issue of Building Safety Certificate.

The Building being used for Good - Luck Public School situated at Begum Pur Extension, Delhi-110041 has been inspected and it is certified that it is structurally safe as per appearance and site verification.

  
21-08-2002  
Executive Engineer (Rohini) II

President  
Madhu Welfare Education Society  
20, Begumpur, Delhi - 110041

Attested



28/8/02  
R. S. PAWAR  
Principal  
G.B.S.S. Ranjit Nagar,  
New Delhi-110008.

दिल्ली नगर निगम




MUNICIPAL CORPORATION OF DELHI  
OFFICE OF THE EXECUTIVE  
ENGINEER (ROHINI)-II  
ROAD NO-44, PITAM PURA VILL.  
DELHI-110034.

No:-EE(Rohini)II/D- 938

Dated :- 21/08/2002

Sub:- Issue of Building Safety Certificate.

The Building being used for Good - Luck Public School situated at Begum Pur Extension, Delhi-110041 has been inspected and it is certified that it is structurally safe as per appearance and site verification.



21-08-2002

Executive Engineer (Rohini) II

President  
Madhu Welfare Education Society  
20, Begumpur, Delhi - 110041

# ARORA ASSOCIATES

★ ARCHITECTS ★ INTERIORS ★ VALUERS

A-108, (MIG), Sector-2, Pocket-00, Near Avantika, Delhi-110085


Phone : 27519229, 27898098, (M) 9811307788

Ref. No. 2011

Dated 16/10/2011

## BUILDING STRUCTURE CERTIFICATE



I, T.C. Arora Architect, visited the Good Luck Public School, Plot No: B-20, Begumpur Extn, Barwala Road, Delhi-110086 and physically checked the structure of the school building. I certify that the structure of the school building is safe and there is no any manufacturing defect.

  
T. C. ARORA  
L. No. S-1564  
A-108, S-2, Pocket-00  
Paham Delhi-85

CERTIFICATE

To whom so ever it is concern, it is certified that I have inspected the building ~~xxx~~ of Good Luck Public School, situated at B-20, Begam Pur, Barwala, New Delhi, and I have prepared the site plan of the said building.

It is also certified that the same is quite fit for running a School in that building.



**S. K. Verma**  
Architect  
W. Wing Near Ch. No. 1  
Tis Hazari Court Delhi

# R. DAYAL & ASSOCIATES

GOVT. APPROVED, ENGINEER'S ARCHITECTS & VALUER'S

Cont. Office : **PIPAL & ASSOCIATES** Ph. : 5769117 (Res.)

Near Treasury Gate, Tis Hazari, Court, Delhi-110 054

**RAMESHWAAR DAYAL**

B. ARCH. M.C.A., A.I.V. (CIVIL)

Regd. Architect Consulting Engineer

Approved Valuer

Regd. No. L.C.A. 87110693 A-1

VALUATION/ESTIMATE OF IMMOVABLE PROPERTY NO.

REF. ....

OWNER :

DATE ....10/6/2002...

## STRUCTURAL STABILITY CERTIFICATE

It is certified that I have inspected the school and its building of GOODLUCK PUBLIC SCHOOL situated at B-20, Begunpur, Barwala Road, New Delhi-110041 and prepared the site plan.

The construction of the said school is safe, sound and pucca. The brick wall cement plastered thereon on both sides. PCC flooring and RCC roofing thereon. Hard and soft wood used in Doors and windows.

There is no danger to the life of inhabitants residing adjoining to the said building. The said building is safe and fit for running the school.

R. Dayal  
10/6

(R. Dayal **RAMESHWAAR**)  
B. Arch., M.C.A., A.I.V.  
Regd. Architect Approved Valuer  
No. CA/87/10693A-1